

**SYLVAN UNION SCHOOL DISTRICT
SYSTEM REPLACEMENT PLAN AS OF JUNE 15, 2020**

Fiscal Year	Carpet	Floor Tiles	Parking Lots	Blacktop Play area	Paint Interior	Paint Exterior	HVAC	Playground Equipment	Playground Fall Surface	Roofing	Fire Alarm	Intercom/Bells
Expected Years	10	15	20	10	15	15	15	15	15	20	25	20
17-18												
18-19												
19-20	US/DO	SO	SO	SC/SO/WO/SY	EU	FR	SC / SH		SO	SC MPR		
20-21	SO/DO	OR	DO	ST				CFB	EU	OR	OR	
21-22	MAS	DO	CFB	CFB	FR	MAS	SO	SY	CFB	EU	DO	
22-23	SO	EU	EU, OR	EU	DS	CR	FR	FR	SH	MPR'S (4)	EU	
23-24	EU		ST	DS	MAS	DS	CFB*	ST	SC	DS	FR/SO	
24-25	CR		DS	FR	CR	SO	DO	SC	WO	CR	CR	
25-26	DS		FR, WO	CR	SO	M&O, FS	M&O, FS	SH	SY	MAS	MAS	FR
26-27	SC		CR	MAS	CFB	SC	CR	MAS	SH	CFB	DS	MAS
27-28	CFB		MAS	SH	DO	CFB	MAS	OR	FR	SC	CFB	CR
28-29	M&O, FS		M & O		SC	ST	DS	CR	OR 18-19	SO	SC	DS
29-30	ST		FS		ST	SH	CFB	WO 18-19		SH	SH	
30-31	SH				SH	WO	SH			WO	ST	
31-32	WO				WO	SY	ST			SY	WO	
32-33	SY				M&O/FS	EU 18-19	WO			OR	M&O	
33-34					SY		SY			EU		
34-35							OR					
35-36							EU					

Note: Field Leveling was removed from plan due to improved procedures to do smaller repairs as needed and better maintain the overall field condition.

Floor tiles- With the floor tiles, our goal is to have them all removed and replaced with polished concrete (where we can). Once that is done, so is the tile.

Ceiling Tiles- The best thing to do for the ceiling tiles is to maintain them and replace the ones that need to be. No sense in replacing entire schools.

Playground equipment- there is no playground equipment at the middle schools.

HVAC * Somerset is 60 Wing Only - Sherwood is 30 Wing Only

CFB is Selected Units Only

	Complete
	In Progress