

<b>Mfg.</b>	<b>Serial #</b>	<b>Asset Tag #</b>	<b>Description</b>	<b>Notes</b>
Motorola	270CHV0213	069387	Portable 2-way radio	Needs repair - no longer supported
Motorola	270CHV0234	069084	Portable 2-way radio	Needs repair - no longer supported
Motorola	514CHV1574	069284	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHV1589	069281	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0539	069270	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0541	069268	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0569	069288	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0577	069339	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0591	069259	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0593	069357	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0597	069224	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0600	069343	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0607	069341	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0608	069300	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0617	069200	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0622	069143	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0624	069124	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0643	069201	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0660	069340	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0663	069237	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0666	069333	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0671	069195	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0673	069204	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0674	069348	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0678	069205	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0679	069330	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0694	069218	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0694	069218	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0700	069214	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0701	069351	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0702	069344	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0708	069371	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0719	069234	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0720	069307	Mobile 2-way radio	Needs repair - no longer supported
Motorola	514CHX0722	069365	Mobile 2-way radio	Needs repair - no longer supported
Motorola	527CRT7339	069507	Mobile 2-way radio	Beyond economic repair