



Home

Project Status eTracker

Inspectors

Accepted Labs

Plan Review Fee Calculator

Project Status Pre-Tracker

Help

Application Summary

Office ID:	03	Application #:	113354	File #:	19-H36
Project Name:	Morningside High School				
Project Scope:	Reconstruction of 1-Girls Locker Building "Q" (A#7889) (Fire Damage)				
Address:	10500 S Yukon Ave				
City:	Inglewood	Zip:	90303		
PTN #:	64634-44	OPSC #:			
Project Type:	School (K-12)	# Of Incr:	0		
Project Class:	Class 1	Special Type:	NA		
Estimated Amt:	\$350,000.00	Contracted Amt:	\$350,000.00		
Change Order Amt:	\$0.00	Final Project Cost:	\$0.00		

Adj Est.Date#1:

Adj Est.Amt#1:

Adj Est.Date#2:

Adj Est.Amt#2:

Received Date: 4/19/2010

Approved Date: 8/11/2010

Approval Ext. Date:

Closed Date: 10/14/2015 10:58:23 AM

Incomplete Submittal Complete Submittal Received Date: 4/19/2010

SB 575

New Campus

Modernization

Required

Auto Fire Detection

Sprinkler System

Included In Plan

Required review services

Access Compliance

Fire & Life Safety

HPS

Structural Safety

Field Review

CGS Review

Special review type

Class.S Reduction

Concurrent Review

Incremental Review

Over the Counter

Energy Efficiency

The Plan meet Title 24 Energy Requirements

Project's new construction exceeds Title 24 by %

Project's modernization exceeds Title 24 by %

Climate Zone: Project's Sq.footage:

EPR Approved Date:

HPI: HPI Points:

HPI Hours:

Energy Notes:

Client's Notes:

DGS Links

- [DGS Home](#)
- [DSA Home](#)
- [DSA News & Events](#)

Tracker Links

Project Status

- [Home](#)
- [Application Summary](#)
- [Project Fee](#)
- [Project Schedule](#)
- [Service Review Status](#)
- [Field Review Status](#)
- [Addenda](#)
- [Change Orders](#)
- [Deferred Approvals](#)
- [Revision](#)
- [Project Professional](#)
- [Project Certification](#)
- [Documents Required List](#)

[Back to Top](#)

[Conditions of Use](#)

[Privacy Policy](#)

[Accessibility](#)

[Contact Us](#)